AI - VI - P - 014 Shaw Property Farm House Rawlings

The Shaw Property Farm House is built in the cottage style of the mid-nineteenth century. It is a frame building covered by board and batten siding, and is two stories high and three bays wide. The windows are two over two lights with shutters and hood. Several stained glass windows are placed on the main facade and around the entrance. One corbeled brick chimney is located centrally to the entire facade.

MARYLAND HISTORICAL TRUST AL-VI-B-014

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

NAME				
NAME				
Shaw Property Frame House				
AND/OR COMMON	56			
Collins' Farm				
LOCATION				
STREET & NUMBER				
Off Rt. 220 Sout	h, .3 mile South			
CITY, TOWN	VICIAIITY OF	CON	GRESSIONAL DIST	RICT
STATE	VICINITY OF	COU		
Maryland			Allegany	
CLASSIFICATION			No Long	ger in use
CATEGORY OWNERSHIP	STATUS		PRE	SENTUSE
DISTRICTPUBLIC	OCCUPIED		_AGRICULTURE	MUSEUM
*BUILDING(S) * PRIVATE	XUNOCCUPIED	-	COMMERCIAL	PARK
STRUCTUREBOTH	WORK IN PROGRESS		_EDUCATIONAL	PRIVATE RESIDE
SITE PUBLIC ACQUISITION	ACCESSIBLE		ENTERTAINMEN	TRELIGIOUS
OBJECTIN PROCESS	YES: RESTRICTED		_GOVERNMENT	SCIENTIFIC
BEING CONSIDERED	YES: UNRESTRICTED		_INDUSTRIAL _MILITARY	TRANSPORTATIO
NAME Wilbur Collins		Toloni	2020 # · ·	720_3532
STREET & NUMBER		rerebi	none #:	(27-3)32
P.O. General Delivery				
CITY, TOWN				zip code
	VICINITY OF		Maryland	21557
LOCATION OF LEGAL DESCR	Liber	#: 454		
COURTHOUSE,			#: 85	
REGISTRY OF DEEDS, ETC. Allegany County	Courthouse			
STREET & NUMBER 30 Washington St	reet			
CITY, TOWN			STATE	
Cumberland			Maryland	
REPRESENTATION IN EXIST	ING SURVEYS			
TITLE				
DATE	EEDEDAL	CTATE	COUNTY	
DEPOSITORY FOR	reveral	_STATE _	COUNTY _LOCA	AL
SURVEY RECORDS CITY, TOWN			STATE	

M-48-014

CONDITION

__EXCELLENT

__DETERIORATED

_GOOD _XRUINS

__FAIR

__UNEXPOSED

CHECK ONE

__ALTERED

CHECK ONE

ZORIGINAL SITE

_MOVED DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Collins board and batten frame house is located off Route 220 South near Rewlings, Allegany County on the east side of the road, three tenths of a mile South of the Rawlings lost Office.

The house consists of a two story, three bay wide """ shaped facade. A two story wing abuts the main block on the rear western side forming the stem of the "T". The building is a frame structure covered with verticle board and batten siding and is supported by a low brick foundation with a plain water table. The roof of the structure is gabled including rafter ends and barge board and is covered with replaced asphalt materials. Windows in the building include double hung wooden sash frames with two-overtwo lights, shutters, and many have deteriorated hoods. Several stained glass windows are placed on the face of the main block and around the entrance. The main entrance is located on the front eastern face and exhibits the original verticle paneled door with transom and stained glass transom lights. An end porch with hipped roof originally covered the front entrance, however it has since deteriorated and collapsed. One corbeled, brick chimney, which is original is located centrally to the entire facade.

The house is rapidly deteriorating and is in near ruins condition.

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

__COMMUNITY PLANNING __ARCHEOLOGY-PREHISTORIC _LANDSCAPE ARCHITECTURE __RELIGION PREHISTORIC LAW SCIENCE __CONSERVATION _1400-1499 __ARCHEOLOGY-HISTORIC __LITERATURE __SCULPTURE _1500-1599 __AGRICULTURE __ECONOMICS __EDUCATION __MILITARY __SOCIAL/HUMANITARIAN __1600-1699 XARCHITECTURE __THEATER __ENGINEERING __MUSIC __1700-1799 __ART __EXPLORATION/SETTLEMENT __PHILOSOPHY _TRANSPORTATION X1800-1899 __COMMERCE __1900-__COMMUNICATIONS _INDUSTRY __POLITICS/GOVERNMENT _OTHER (SPECIFY)

__INVENTION

ca. 1870

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

SPECIFIC DATES

The Shaw Frame House is one of four properties owned by Major Alexander Shaw, an officer with the Union Army during the Civil War. Major Shaw was, in all probability, one of the richest men in Allegany County especially considering the fact that his major source of income came from agriculture. The Frame House was built by Major Shaw sometime after he aquired the property in 1874. Major Shaw used the first floor of the building as an office while the 2nd floor was used to house servants who worked in the main house. 1

Architecturally, the building is a good example of the "cottage style" popular in the Victorian Period. Although it is deteriorating rapidly, many fine details are still visable such as stained glass transom lights and windows on the first floor, the hoods over the windows and the fine corbeled chimney.

1. Interview with Mrs. Helen Hinkle, Treasurer Allegany County Committee of the Maryland Historical Trust. 8/18/76

9 MAJOR BIBLIOGRAPHICAL REFERENCES

STREET & NUMBER

CITY OR TOWN

10 Park Lane

Frostburg

AL-VI-B-014

TELEPHONE

STATE

689-8486

Maryland

Allegany County Land Records, Cumberland , Maryland

	PHICAL DATA OMINATED PROPERTY	968.4 acres					
VERBAL BOL	JNDARY DESCRIPTION			1			
LIST AL	LL STATES AND COUNTIE	S FOR PROPERTIES	S OVERLAPPING ST	ATE OR	COUNTY BOL	INDARIES	
LIST AL	L STATES AND COUNTIE	S FOR PROPERTIES	S OVERLAPPING ST	ATE OR	COUNTY BOL	INDARIES	
	LL STATES AND COUNTIE	S FOR PROPERTIES		TATE OR	COUNTY BOL	INDARIES	
STATE	L STATES AND COUNTIE	S FOR PROPERTIES	COUNTY	ATE OR	COUNTY BOL	INDARIES	
STATE	LE STATES AND COUNTIE	S FOR PROPERTIES	COUNTY	ATE OR	COUNTY BOL	INDARIES	
STATE		S FOR PROPERTIES	COUNTY	ATE OR	COUNTY BOL	INDARIES	
STATE STATE			COUNTY				
STATE STATE	REPARED BY	Program Coordi	COUNTY county inator of All.	Co. I			

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

INVENTERY NO. <u>Al-VI-</u> B-014	Liber - 454
DATE: 6/16/76	Folio - 85
REMORES ING: Drastic, moderate, minor	968. 4 acres
NAME OF PROPERTY: Part of old Sho	aw farm Property
LOCATION OF PROPERTY: . 3 Mile South of	Rawlings Along Rt. 200 South
DIRECTION DUELLING FACES: East	J
NAME OF OWNER: Wilbur Collins	729 - 3532
ADDRESC: P.O Box	
Rawlings Marylan	d 21557
STORIES: 1() 2(1) 3() 4() 5() 6() BAYS: 1() 2() 3() 4() 5() 6() 7() ()
wings, Additions: Roa. Wing	
Dwelling Shape: (square, cross, rectangular)	Shaped
WALL CONSTRUCTION:	
<pre>(/) FRAME: Bevel, clapboard, weatherboard, wood s () BRICK: Bond type- common, English, Flemish. () STONE: Bond type- rubble, ashlar (random or r () LOG () Other: Coverings</pre>	Shingles, board & batten (type?) Verticle Sketch variants. egular), quoins-plain, rusticated
WALL FEATURES: BELT COURSE, RILASTERS, OTHERS FOUNDATIONS: HIGH, LOW, BRICK, STONE WATER TABLE: FLAIN, BEVELED, MOULDED BRICK	Plair
WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6 Stained Glass Lights pegged () nailed() wide	6() 9/9() other() Hoods () narrow() mitred() pediment()
ENTRANCE, DOORS: LOCATION: Last HARDWARE: original() replaced(FAN LIGHT, TRANSOM SIDE LIGHTS, P. Caneled Verticle Horizontal Board	IAIN Irauson Light Stained
CORNICE, BARGE, FAVES: (crown, fascia, soffit, bed) original() replaced() Rafter End	Barge Board s, Modillions, Dentils, Frieze, Architrave
RCCF: GABLE FRONT, GABLE FLANK, HIP, SHED, MANGARD, MATERIAL: wood shingles, slate, tin, esphalt	GAMBREL, FLAT, FORMERS #
FORCHES: SHAFE OF ROOF - shed() hip(gable()	
CHIMILYS: NUMBER / ERICK() STONE() CORDELED LOCATION: Flush end() Inside end() Co	D() original() replaced () utside end() Central() Interior ()
ARCHES: Door and window: Keystone, Tlat. Segmental	, Semicircular
CCINETTS: Use - No Longe, used Significance - Arch. Date Constructed - Mid 19th Century Condition - Ruins	

Key points regarding interior architecture.

1. Floor plan
No through hall--How many rooms long and deep?
Where is stairway? Straight or winding?

With through hall--Rooms on both sides? How many?

Rooms on one side only? How many?

Is stair in through hall?


Open or enclosed? Straight--one run. Straight--landing
How many? Curved.

If not in hall, where is stair?

- 2. Wall finish: plaster, paneled, board partition Note presence of chair rail, cornice, etc.
- 3. Doors: on the inside of exterior doors, note the presence of applied flush boards and their direction (diagonal, vertical, horizontal). In general are doors paneled or ledge or other?
- 4. Door and window trim: plain, architrave; fluted, reeded; pilasters

prome but product on which he will be made on and production and respondent

5. Kitchen: Where is original if extant or known (marked by very large fireplace)? Separate building; wing to principal dwelling; within principal dwelling? On which floor of any of the above?





Shaw Frame House A1-U1-B-014 Rt 220 South - Off .3 Mile S. of Rawlings John E. Nelson 6/16/76 South



AL-VI-B-014 SHAW PROPERTY FRAME HOUSE

6/16/1976 - John Nelson